			1. CONTRACT/TASK ORDER NUMBER					
INSPECTION REPORT ON WORK UNDER CONTRACT					GS05P13SID0086 /GSP0517GC0051			
2. LOCATION (Street, City, and State)					3. BUILDING			
211 S Clark Street, Chicago, IL					US Post Office - Loop Station IL0235FC			
4. CONTRACTOR'S NAME AND ADDRESS					5. TYPE OF WORK	6. CONTRACT FOR		
Charpie Construction Co., Inc 6617 North Avondale Chicago, IL 60631					Demo, Storage Fence Install, Minor Electrical, Painting, Repair.	REPAIR AND ALTERATIONS     NEW CONSTRUCTION		
7. PROJECT NUMBER	8. DATE OF NOTICE 9. ORI TO PROCEED PRI			AL CONTRACT	10. CUMULATIVE CHANGE ORDERS/MODIFICATIONS	11. CONTRACT PRICE TO DATE		
RIL11505	07/11/2017 \$84,200			00 \$ 14,523.00		\$ 98,723.00		
12. LIQUIDATED DAMAGES PER DAY			13. COI	MPLETION DATE		14. PERCENTAGE OF COMPLETION		
	a. CONTRACT	b. REVISE	D	c. ESTIMATED	d. ACTUAL	a. ACTUAL	b. NORMAL	
\$ 250.00	8/1/17				7/28/17	.95	95%	
15. A-E FIRM		•		16. CM FIRM		•		
Bailey Edward Design, Inc				N/A				
35 W. Wacker Drive	-							
17. CMa ENGINEER				18. GSA INSPECTOR				
N/A				Ransom Gillespie				
19. TYPE OF INSPECTION 20. DATE OF LAST INSPECTION			21. DATE OF THIS INSPECTION			23. PAYMENT RECOMMENDED  YES NO RETAINAGE RECOMMENDED		
PROGRESS X FI	NAL POST FINAL			07/28/2017	X YES NO		X NO	
					RCE, DELAYS OR CORRECTIVE AC			

RECOMMENDATIONS. NOTATE ANY SIGNIFICANT CHANGE ORDERS OR MODIFICATIONS ISSUED SINCE THE LAST INSPECTION AND THE PERCENTAGE OF COMPLETION TO DATE.

see attached form 2480 List of Defects and Omissions

5. COR APPROVAL	SIGNATURE	(b) (6)	DATE	
			08/17/2017	

**General.** GSA 220 shall be used for documenting contract compliance by the Contracting Officer's Representative (COR). This form shall be used on all construction contracts awarded under new construction and repair and alteration programs. The GSA 220 provides documentation of the required separation of duties between the ordering and inspecting functions. The COR is responsible making sure that required inspections of contract work are performed and that the work meets contract requirements. The COR may inspect the work or may oversee the inspection by an independent 3rd party construction manager advisor contract employee. The COR is the GSA responsible party for accepting the work for payment purposes.

## FINAL INSPECTION

If this report covers "final" inspection, the procedure outlined below shall be followed in connection with defects and omissions found:

- 1. As soon as possible after inspection give the contractor a list of all items necessary to properly complete the contract with a demand that each item be corrected or supplied WITHOUT DELAY. Furnish the Building Manager a copy of letter to contractor with list of items of defects and defects were entirely corrected. There may be items on the list which, in the opinion of the Inspector and the COR, should remain as installed rather than be corrected. In such cases the COR shall furnish the Contracting Officer full information and recommendation and advise the contractor that the Contracting Officer will render the decision thereon.
- 2. Forward to the Regional Office the final report, three copies of the list of items of defects and omissions given to the contractor, and a SEPARATE supplementary statement in duplicate giving an estimated cost of completing in accordance with contract requirements each and every item should it become necessary for the Government to complete the work.

Items for which, in the opinion of the Inspector, completion is not practicable should be indicated in the supplementary statement. A recommendation should be given for each of such items as to the amount, if any, to be deducted from the contract price because of noncompliance with contract requirements.

Copy of the supplementary statement should NOT be given to either the contractor or to the Building Manager.

3. The Inspector should indicate the date on which work was substantially completed.

Attention is called to provisions of General Conditions requiring contractors to submit written notices of readiness for final inspection and the liability of contractors for reinspection costs. If the Inspector considers an extra final inspection necessary, it should be stated on the report.

## **REINSPECTION COSTS**

Costs incurred in making extra final inspections shall be forwarded in separate statement form. These costs shall include salary, subsistence, transportation and miscellaneous expenses. Costs shall be based upon the time involved in making inspection as well as time and travel involved in reaching place of inspection, including time and travel in reaching next point visited.

## LIST OF DEFECTS AND OMISSIONS

PAGE 1 OF **1** 

		1. BUILDING LO	CATION			2. PROJECT TITLE	·		
					STATE IL	GSA Loop Station SSA P-Level S		rage	
Chicago 3. CONTRACT NO./WORK ORDER NO. 4. INSPECTION				5.	TYPE OF IN	<u> </u>	6. THIS LIST CONCERNS		
DATE				_		ESS PARTIAL FINAL			
SSA PLS 01 / 16034-17-03 07/28/2017					× FINAL		X ARCHITECTURAL STRUCTURAL		
7. NAME OF CONTRACTOR						8. NAME OF INSPECTING ET			
Charp	e Construction	on				James Auler, Bailey Edward Design, Inc.			
9. ITEM NO.	10. SPEC. REF. PARA. NO. AND/OR DRAWING NO.	11. DESCRIPTION OF DEFECT OR OMISS				SION	12. DATE CORRECTED	13. CORRECTED BY (Name)	
1	FP-1	Connect POTS / Standard telephone line							
2	FP-1	2'-9" section of fence missing							
3	FP-1	Keys for fence gates							
4	FP-1	Sprinkler head cages							
5	FP-1	Paint holes left by removing conduit at PL84							
6	FP-1	Provide electrical receptacle covers							
7	FP-1	Black wax overpour at door, jambs, walls (Typical)							
8	FP-1	Missing gates at fence							
9	FP-1	Four (4) bolts at gusset plates for fence							
10	FP-1	Attach cove base at PL47							
11	FP-1	Cracks at levelling compound							
12	FP-1	Both doors to close and lock at PL45 (Anchor jambs and frames)							
13	FP-1	Check and tighten all bolts at fence							
14	FP-1	Chalk line on floor at fence							
15	FP-1	Bulbs out at PL47							
16	FP-1	Paint bubbles at PL45							
17	FP-1								
18	FP-1								
19	FP-1								
20	FP-1								
21	FP-1								
22	FP-1								